Closure Completion Notification for Closure by Removal

September 26, 2024 Closure Completion Notification John E. Amos Plant Bottom Ash Pond Complex

On September 4, 2024, the John E. Amos Plant Bottom Ash Pond Complex was transitioned to closure status in accordance with 40 CFR 257.102. This notice of completion of closure is being placed in the operating record in accordance with 40 CFR 257.102(h).

Effective with the Closure Completion Notification, the former ash storage site is no longer a CCR unit. The following operating record documents are no longer required going forward:

- Hazard Potential Classification
- Emergency Action Plan
- Face to Face Meeting Documentation for EAP
- History of Construction and Revisions for Surface Impoundments
- Structural Stability Assessments
- Safety Factor Assessments
- Fugitive Dust Plan
- Inflow Design Flood System Control Plan

CLOSURE CERTIFICATION BY QUALIFIED PROFESSIONAL ENGINEER

I certify that the John E. Amos Bottom Ash Pond Complex has been closed in accordance with the most recent written closure plan specified by paragraph §257.102(b) and the requirements of section §257.102.

David Anthony Miller

Printed Name of Licensed Professional Engineer



David Anthony Miller

Signature

22663

License Number

West Virginia

09.26.2024

Licensing State

Date



Charleston Office 500 Lee Street, East, Suite 700 Charleston, West Virginia 25301 T 304.926.8100F 304.926.8180

August 5, 2024 Project No. R210487.00

Mr. Brian G Palmer, PE Principal Engineer AEP 1 Riverside Plaza Columbus, Ohio 43215

AEP – John E. Amos Bottom Ash Complex Pond Closure - Completion Putnam County, West Virginia

Dear Mr. Palmer:

GAI Consultants, Inc. (GAI) appreciates the opportunity to provide American Electric Power Service Corporation (AEP) with the Quality Assurance / Quality Control and certification services for the closure of the Bottom Ash Complex at the John E. Amos Plant located in Putnam County, West Virginia.

This letter documents that removal of the coal combustion residual material from the bottom ash complex was completed in substantial compliance with the Construction Documents completed by Worley, the Closure Plan and 40 CFR 257.102(c).

The areas of the bottom ash complex were certified as they were completed. The following presents the areas and certification date:

- Pond 1B April 21, 2023
- Clearwater and Reclaim Ponds July 24, 2023
- Pond 1A August 5, 2024

If you have any questions or require additional information, please contact me at 681.245.8866 (c.straley@gaiconsultants.com).

Respectfully submitted.,

GAI Consultants, Inc.

Charles F. Straley, PE DN: C=US, Charles F. Straley, PE DN: C=US, E=c:straley@gaiconsultants.com, O="GAI Consultants, Inc.", CN="Charles F. Straley, PE" Date: 2024.08.05 15:16:48-04'00' Charles F. Straley, PE, PLS Quality Assurance Officer / Certifying Engineer Engineering Director / Senior Associate

CFS

5.0 PE Certification


Based on the observations performed by GAI Consultants, Inc. personnel, I hereby certify that the removal of CCR material to be visually removed and one-foot additional undercut within Pond 1B and along the southern edge of Pond 1A of the CCR/ELG Project Bottom Ash Pond Closure and Repurposing Project at the John E. Amos Plant near Winfield, West Virginia (WV), as shown on the Worley Construction Drawings has been completed in substantial compliance with the Construction Documents, the Closure Plan and 40 CFR 257.102(c).

This document clarifies "certification" for the excavation of CCR material to be visually removed and an additional one-foot of undercut within Pond 1B and along the southern edge of Pond 1A of the CCR/ELG Project Bottom Ash Pond Closure and Repurposing Project. This certification is strictly limited to CQA observations of CCR removal and does not include the groundwater monitoring and compliance aspect of the CCR Unit closure by removal criteria, as required by 40 CFR 257.102(c).

The definition of certify as used herein is: Certify means to state or declare a professional opinion of conditions whose true properties cannot be known at the time such certification was made, despite appropriate professional evaluation. A design professional's certification in no way relieves any other party from meeting requirements imposed by contract or other means, including commonly accepted industry practices.

Bearing the above in mind and based on the results of monitoring of construction efforts during the project and review of the survey points; GAI's professional opinion is that the CCR material within Pond 1B and along the southern edge of Pond 1A and additional one-foot undercut of the CCR/ELG Project Bottom Ash Pond Closure and Repurposing Project meets the requirements as set forth by the project documents and the CCR Rule.

Charles F. Straley, 뇬 West Virginia Number 11842





5.0 PE Certification

Based on the observations performed by GAI Consultants, Inc. personnel, I hereby certify that the removal of CCR material to be visually removed and one-foot additional undercut within Clearwater & Reclaim Ponds of the CCR/ELG Project Bottom Ash Pond Closure and Repurposing Project at the John E. Amos Plant near Winfield, West Virginia (WV), as shown on the Worley Construction Drawings has been completed in substantial compliance with the Construction Documents, the Closure Plan and 40 CFR 257.102(c).

This document clarifies "certification" for the excavation of CCR material to be visually removed and an additional one-foot of undercut within Clearwater & Reclaim Ponds of the CCR/ELG Project Bottom Ash Pond Closure and Repurposing Project. This certification is strictly limited to CQA observations of CCR removal and does not include the groundwater monitoring and compliance aspect of the CCR Unit closure by removal criteria, as required by 40 CFR 257.102(c).

The definition of certify as used herein is: Certify means to state or declare a professional opinion of conditions whose true properties cannot be known at the time such certification was made, despite appropriate professional evaluation. A design professional's certification in no way relieves any other party from meeting requirements imposed by contract or other means, including commonly accepted industry practices.

Bearing the above in mind and based on the results of monitoring of construction efforts during the project and review of the survey points; GAI's professional opinion is that the removal of CCR material within Clearwater & Reclaim Ponds and additional one-foot undercut of the CCR/ELG Project Bottom Ash Pond Closure and Repurposing Project meets the requirements as set forth by the project documents and the CCR Rule.

Charles F. Straley, PE West Virginia Number 11842



5.0 **PE Certification**

Based on the observations performed by GAI Consultants, Inc. personnel, I hereby certify that the removal of CCR material to be visually removed and one-foot additional undercut within Pond 1A of the CCR/ELG Project Bottom Ash Pond Closure and Repurposing Project at the John E. Amos Plant near Winfield, West Virginia (WV), as shown on the Worley Construction Drawings has been completed in substantial compliance with the Construction Documents, the Closure Plan and 40 CFR 257.102(c).

This document clarifies "certification" for the excavation of CCR material to be visually removed and an additional one-foot of undercut within Pond 1A of the CCR/ELG Project Bottom Ash Pond Closure and Repurposing Project. This certification is strictly limited to CQA observations of CCR removal and does not include the groundwater monitoring and compliance aspect of the CCR Unit closure by removal criteria, as required by 40 CFR 257.102(c).

The definition of certify as used herein is: Certify means to state or declare a professional opinion of conditions whose true properties cannot be known at the time such certification was made, despite appropriate professional evaluation. A design professional's certification in no way relieves any other party from meeting requirements imposed by contract or other means, including commonly accepted industry practices.

Bearing the above in mind and based on the results of monitoring of construction efforts during the project and review of the survey points; GAI's professional opinion is that the CCR material within Pond 1A and additional one-foot undercut of the CCR/ELG Project Bottom Ash Pond Closure and Repurposing Project meets the requirements as set forth by the project documents and the CCR Rule.

Charles F. Straley, PE Vest Virginia Number 11842



MONITORING AND EMERGENCY ACTION PLAN FOR THE JOHN E. AMOS BOTTOM ASH POND COMPLEX ID # 07918 WINFIELD, PUTNAM COUNTY, WEST VIRGINIA

Owned by:

John E. Amos Plant Appalachian Power Company 1530 Winfield Road Winfield, WV 25213

Prepared By:

American Electric Power Service Corp. One Riverside Plaza Columbus Ohio 43215

November 2023



TABLE OF CONTENTS

| | <u>Page</u> |
|--|-------------|
| Introduction | 2 |
| Purpose of Plan | 2 |
| Brief Overview of Dam and Observed Problems | |
| List of All Known Problems Concerning the Dam | 2 |
| Driving Directions to Dam | |
| How to Use This Document | |
| Plans for Training, Exercising, and Updating the Emergency Action Plan | |
| Training and Updating | |
| EAP Exercises | 3 |
| Location Map | 4.5 |
| Summary and index | |
| Part 1 Monitoring Plan and Inspection Schedule | |
| | |
| Section A Normal Conditions | |
| Section B Adverse Conditions | |
| Section C Standby Alert | |
| Section D Evacuation Conditions | |
| Section A Notification of Agencies | |
| Section B Evacuation Notification of Downstream Persons | |
| Section C Evacuation Notification Map | |
| Part III Post Evacuation Notification Action | 19 |
| Section A No Failure of Dam | |
| Section B Failure of Dam | 19 |
| Part IV Administrative and Record Keeping | 20 |
| Section A Signature and Distribution List | |
| Section B Inspection Record | |

Appendices

- A EAP Training Record
- B Unusual or Emergency Event Log
- C Emergency Contacts

Note:

- The November 2023 Emergency Action Plan revision reflects changes in plant contacts:
- Relocation of the Putnam County Sheriff Office. •
- Noah Alvis added to Putnam County OEM. •
- Paul Massie as John Amos Plant Manager. •
- Bryan Brunton as Geotechnical Engineering Manager •
- Relocation of the WV Emergency Management Division •

EMERGENCY ACTION PLAN CFR 257.73 (a)(3) BOTTOM ASH PONDS COMPLEX DIKES JOHN E AMOS PLANT

GERS-21-021

PREPARED BY DATE Christy L. rence

REVIEWED BY Br & Value


DATE 10/18/2021

Brian G. Palmer, P.E.

APPROVED BY

DATE 10/18/2021 Gary F ZychJP.E.

Manager - AEP Geotechnical Engineering



I certify to the best of my knowledge, information, and belief that the information contained in Emergency Action Plan meets the requirements of 40 CFR § 257.73 (a)(3)

Note: Reviewed and no technical changes from the version signed and sealed April 17, 2017.

Monitoring and Emergency Action Plan, 11/1/2023

American Electric Power, John Amos Bottom Ash Complex ID # 07918, Winfield, Putnam County, West Virginia

Introduction

Purpose of Plan

The purpose of this document is to provide for monitoring of the John E. Amos Plant Bottom Ash Pond Complex under various conditions so that an emergency situation at the complex will be observed promptly and reported to agencies and persons who may be affected. This document also provides a plan for the orderly notification and evacuation of downstream residents to a place of safety in the event of a potential or actual dam failure.

Brief Overview of Dam and Observed Problems

The John E. Amos Plant Bottom Ash Pond Complex consists of two ash ponds, a reclaimed water pond, and a treatment pond. The main dike is an earthen structure 30 feet high and impounding a maximum volume of water of 950 acre-feet. The primary spillway consists of a 24 inch by 36 inch elliptical pipe. The dam has an emergency spillway consisting of two 36-inch diameter pipes through the main dike, discharging into Bill's Creek. The dam normally has a freeboard (vertical distance in feet between the normal reservoir elevation and the top of the dam) of 5 feet.

List of All Known Problems Concerning the Dam

No known problems at this time.

Driving Directions to Dam

Starting at the intersection of First Avenue (WV-25 W) and Lock Street in Nitro, WV, travel north on First Avenue (WV-25 W) for 2.1 miles before turning right to merge onto I-64 W. After 1.1 miles, take Exit 44 toward US-35/St. Albans. Turn left in 0.2 mile, at the end of the exit ramp, toward Winfield Road. Take the freeway 0.6 mile and turn left onto WV-817 N/Winfield Road. Travel 2.6 miles on WV-817 N/Winfield Road and enter the plant on your right. Located in northern part of plant property.

Coordinates for the dam are 38.479529, -81.830207 (NAD83).

How to Use This Document

Persons using this plan will find a sequence of actions to implement depending on quantities of rainfall and site conditions. A summary of where to find specific monitoring, reporting and evacuation requirements can be found in the Summary and Index.

Plans for Training, Exercising, and Updating the Emergency Action Plan

The purpose of an annual review and training of the EAP is to ensure that all contact information listed in the notification charts is accurate and that the owner/operator of the dam and local first responders are familiar with the EAP and understand their respective roles in responding to a dam emergency.

Training and Updating


Local County Emergency Management Agency/first responders should be invited to attend an annual training for a face-to-face meeting and to have a general sense of familiarity with the dam site. The plant manager, or a designated representative, will be responsible for updating the EAP as necessary and distributing copies of the revisions. Copies of all updated or revised pages will be provided to all designated holders of the EAP.

EAP Exercises

In addition, the dam owner/operator should work with local emergency management and other first responders to determine what opportunities exist to conduct or participate in a dam related EAP exercises. Records/summaries of all EAP exercises should be documented in the EAP (Appendix A).


Any changes to the EAP stemming from justified concerns raised by anyone participating in any EAP exercise should be documented and distributed to all holders of the EAP.


Location Map



Configuration Map

• ÷





(

F

8

Monitoring and Emergency Action Plan. 11/1/2023

American Electric Power, John Amos Bottom Ash Complex ID # 07918, Winfield, Putnam County, West Virginia

SUMMARY AND INDEX

Part I - Monitoring Plan and Inspection Schedule

Section A – Normal Conditions

Dam will be inspected according to the prescribed schedule and checked for items specified on the dam inspection checklist.

Section B – Adverse Conditions

Dam will be inspected within 24 - 48 hours of the conditions described.

Section C – Standby Alert

Dam has specific problem(s), which could lead to an evacuation condition. Constant surveillance is initiated and a Standby Alert is issued. Emergency repairs begin, if possible.

Section D – Evacuation Conditions

A dam failure is imminent or has occurred. Notification will be initiated and an evacuation order will be given by approved AEP personnel, if warranted.

Part II – Emergency Action and Evacuation Plan

Section A – Notification

The residences of the flood inundation area will be notified to evacuate by plant personnel if failure of the dam is imminent or has already occurred. Notification will also be given to the Putnam County Office of Emergency Services (OES) to commence evacuation. Notification of the emergency will also be given to other appropriate agencies.

Section B – Evacuation of Downstream Persons

A narrative of the evacuation procedures is provided.

Section C – Evacuation Maps

Not Applicable. No structures are located within the inundation area.

Part III – Post Evacuation Notification Procedure

Section A – No Failure of the Dam

Cancellation of evacuation order occurs.

Section B – Failure of the Dam

Coordination with emergency relief agencies continues.

Part IV- Administration and Record Keeping

Section A – Signature and Distribution List

Section B -- Maintenance and Inspection Record

Appendices

- A EAP Training Record
- B Unusual or Emergency Event Log
- C Emergency Contact
- D Inundation Map

Monitoring and Emergency Action Plan. 11/1/2023

American Electric Power, John Amos Bottom Ash Complex ID # 07918, Winfield, Putnam County, West Virginia

Part I – Monitoring Plan and Inspection Schedule

HOMELAND SECURITY. In the event of sabotage or security breach **that may lead to failure of the dam**, the Putnam County Office of Emergency Management will be notified immediately by calling 911. Proceed immediately to Part I, Section C or D as appropriate.

Section A – Normal Conditions

Items to be inspected during normal conditions (dry weather or occasional rainfall [<3" in 24 hours]) are to include, but are not limited to the following:

- 1. reading of instrumentation or operation of emergency pumps;
- 2. Inspection of trash racks, spillways, seepage zones;
- 3. Check for embankment cracking, slumps, sinkholes, bulges; and
- 4. Equipment failure and vandalism

Responsibility Action Plant Personnel * 1. Inspect monthly or as appropriate to condition of dam. 2. If an "Unusual Condition with Minimal Potential Plant Personnel * for Dam Failure" is found, contact AEPSC's Geotechnical Engineering Section; report on inspection checklist and increase inspection frequency in accordance with the Geotechnical Engineering recommendations. 3. If a serious problem is observed, which is classified as a "Serious but Non-Emergency -Plant Personnel * Potential Dam Failure is Developing," proceed to Section C - Standby Alert. If an "Emergency – Failure is Imminent or has Plant Personnel * Occurred" feature is observed, proceed to Section D - Evacuation Conditions. 5. Annual geotechnical safety inspection **Professional Engineer**

* Appropriate names, addresses, and phone numbers are provided in Appendix B.

| Performance Level of Dam | Malfunctions or Undesirable Features | Actions to Be Taken By Field Personnel (In Order Indicated) | |
|--|--|---|--|
| Non- Emergency Minor Deficiency | Damaged instrumentation Sloughing Rodent Burrows Surface erosion Trees and tall vegetation Poor vegetation cover Deteriorated riprap | Report on inspection checklist. Write repair order, if appropriate | |
| Adverse Conditions Unusual Condition with Minimal Potential for Dam Failure | Cracks parallel or transverse to dam Soft zones on downstream face or toe Previously undetected springs with clear water and stable flow rate on face of dam or abutments Excessive settlement of crest | Contact AEPSC Geotechnical Engineering Section. Report on inspection checklist. Increase frequency of inspection as necessary. | |
| Standby Alert Potential Dam Failure is Developing | The formation of new springs with turbidity or a change in flow characteristics from existing springs on the downstream face or abutments including an increase in flow and/or turbidity Pipes, cavities, or holes which could be attributed to internal erosion even without evidences of seepage Clogged drains Slides with no seepage and that do not reach the dam crest Noticeable increase in amount of foundation or abutment seepage or piezometric level for no apparent reason | Notify Team Leader who in turn should issue a Standby Alert. Contact AEPSC Geotechnical Engineering manager/engineer. Determine appropriate advisory notification actions. Initiate daily or more frequent surveillance program. Read all field instrumentation daily. Report on inspection checklist. | |
| Emergency/ Evacuation Conditions Failure is Imminent or Has Already Occurred | Overtopping or activation of emergency spillway Breach or slide below the waterline, which reaches the dam crest and/or seeps water Springs on abutment or downstream slope with muddy water and progressively increasing flow rate | Notify Team Leader who in turn should issue a Notification. Continue 24-hr surveillance program, if possible. Report on inspection checklist | |

Table 1 **Condition Response Table**

Section B – Adverse Conditions

Items to be inspected during adverse conditions heavy or extended rainfall (>3" in 24 hours), flash flood warnings, snow-melt or serious new problems found under normal conditions) are to include, but are not limited to the following:

- 1. Embankment stability including any signs of erosion, cracking, slumps, sinkholes, bulges, and sloughing.
- 2. Operation of discharge pumps, and inspection of pipes, trash racks, spillways, spillway discharge levels,
- 3. Inspection of reservoir elevation and freeboard, seepage zones, and equipment failure

EARTHQUAKE Occurrence of an earthquake of sufficient magnitude to cause structural damage to buildings or property in the general area of the dam shall be considered an "adverse condition." Damage from an earthquake may be internal to the dam and problems may not appear for days or weeks after the event. The dam shall be inspected immediately after the quake and daily for several weeks thereafter. Attention should be directed to looking for cracks, slips, new wet or seepage areas and leakage, both on the face of the dam and in the natural ground areas downstream and at the abutments of the dam.

Action

Responsibility

| 1. | Inspect dam and appurtenance as per the checklist within 24 hours of adverse conditions. | Plant Personnel * |
|------------|---|-------------------|
| 2 . | If a "minor deficiency" is found, report on inspection checklist and write a repair order, if appropriate. | Plant Personnel * |
| 3. | If an "Unusual Condition with Minimal Potential for Dam Failure" is found, contact AEPSC's Geotechnical Engineering Section; report on inspection checklist and increase inspection frequency in accordance with the Geotechnical Engineering recommendations. | Plant Personnel * |
| 4. | If a serious problem is observed, which is classified as a "Serious but Non-Emergency – Potential Dam Failure is Developing," proceed to Section C – Standby Alert. | Plant Personnel * |
| 5. | If an "Emergency – Failure is Imminent or has Occurred" feature is observed, proceed to Section D – Evacuation Conditions. | Plant Personnel * |

* Appropriate names, addresses, and phone numbers are provided in Appendix C.

Section C – Standby Alert

When the condition of dam has deteriorated or water rises to within 3 feet below the crest of the embankment a standby alert is to be issued according to the action list below. Items to be inspected or accomplished under these conditions are the following

- 1. reservoir elevation and freeboard,
- 2. seepage zones, embankment cracking or piping, slumps, sinkholes, bulges, and equipment failure

Action

- Notify Team Leader and begin constant surveillance of dam. Read all field instrumentation daily and report on inspection checklist.
- 2. Standby Alert shall be issued in accordance with the Standby Alert advisory below.
- 3. Respond to notification of Standby Alert.
- 4. If warranted, start emergency communications to involved parties based upon the continuing deterioration of site conditions. Request additional assistance as necessary. If possible, attempt to lower the reservoir pool elevation by removal opening drain gate valve.
- 5. Evaluate the dam and problem areas for corrective action.
- Commence corrective/ emergency repairs, if possible.**
- Start emergency communications network, if necessary, based upon the continuing deterioration of the site conditions. Request additional assistance as necessary

Responsibility

Plant Personnel *

Team Leader *

DWWM Dam Safety 1-800-642-3074

Putnam County OES (304) 586-4920

Putnam County Sheriff (304) 586-0256 or Plant Personnel

Plant Personnel & AEPSC Geotechnical Engineering Section

Engineering Section Plant Personnel

Putnam County OEM (304) 586-4920

Putnam County Sheriff Department (304) 586-0256

Winfield Volunteer Fire Department (304) 586-3555

8. If a problem is observed which could lead to failure, proceed immediately to Section D.

Plant Personnel *

* Appropriate names, addresses, and phone numbers are provided in Appendix C.

The following Advisory will be issued to the agencies listed below by the Amos plant manager or AEPSC. The responsible person notifying the agencies should note the date, time, and name of the contact person.

<u>Advisory</u>

The responsible person shall phone or contact each agency listed below in sequence and cover the following items:

Check when completed:

| identify yourself refer to the dam by name, location and ID number (on title page) advise the person contacted that you are calling as required by the monitoring and emergency action plan state the condition of the dam state that a standby alert is declared advise the person contacted of any requested assistance or action answer any questions | | | | |
|---|---------------------------------|--|--|--|
| Check when notified | Phone | | | |
| WVDEP – DWWM Dam Safety | (800) 642-3074 (24-hour number) | | | |
| Putnam County OEM | 911 or (304) 586-4920 or | | | |

Section D – Evacuation Conditions

In the event that the condition of the dam has deteriorated to the point where failure is likely to occur, including overtopping of the earthen dam, cracking, piping, spillway failure or obstruction, obvious deformation of the dam, etc the following evacuation procedures should be followed:

Action

- 1. Continue constant surveillance of the dam and monitor the conditions affecting the dam.
- 2. If evacuation notice is given, proceed immediately with Part II.

Responsibility

Plant Personnel, AEPSC, or DWWM Dam Safety Section 1-800-642-3074

(304) 586-0246 (24-hour number)

Plant Personnel, AEPSC, DWWM Dam Safety Section 1-800-642-3074, or

Putnam County OEM (304) 586-4920

Putnam County Sheriff Department (304) 586-0256

Winfield Volunteer Fire Department (304) 586-3555

Refer to Appendix C for a complete listing of all emergency contacts associated with Putnam County.

Part II – Emergency Action and Evacuation Plan

Section A - Notification of Agencies

| 1. | Issue Notification as per the chart in |
|----|--|
| | Appendix C. |

2. Notify agencies not on-site using the checklists below

Responsibility

Team Leader, AEPSC, or DWWM Dam Safety

Team Leader

Notification:

Action

"This is <u>(Name)</u> of <u>(Company)</u> notifying you that failure of the Amos Plant Bottom Ash Complex Dam is imminent/ has occurred. Please take emergency action to evacuate downstream residents."

The responsible person notifying the agencies listed on the notification chart should note the date and time of such notification.

| Check when notified: | Phone |
|-------------------------|--|
| DWWM Dam Safety Section | 1-800-642-3074 |
| Putnam County OEM | 911 or (304) 586-4920 or (304) 586-0246 |

Section B – Evacuation Notification of Downstream Persons

In accordance with WV Code 22-14-10, it is the responsibility of the dam owner to notify downstream persons, if county emergency authorities are not available or are unable to notify downstream persons.

There are no structures located within the anticipated inundation zone. No evacuations are required as part of this plan. The inundated area is depicted on Figure 2 (Appendix D).

Note to evacuating authorities: No person may be ordered to leave or to be physically removed from the evacuation area against their will. Notification to persons and providing of assistance to persons in the evacuation area should fulfill agency responsibility under this section of the plan.

In the event that an evacuation is necessary, all willing people inhabiting structures within the "Evacuation Area" as shown on the Evacuation Notification Map will be evacuated to a secure location in coordination with the Putnam County Office of Emergency Management (OEM). Initially those affected persons will be evacuated to the parking lot off main plant entrance near the P100 building close to and away from the dam location. Other evacuation meeting areas could be used as approved by the Putnam County OEM.

Action

- 1. Notification of downstream persons. Plant personnel will notify such residents by phone and in person to initiate the evacuation process.
- Contact and transport downstream residents to point(s) of safety with priority to the infirm or disabled. The Amos plant training center is considered a point of safety.
- Establish a command post at the Amos Plant Training Center suggested to direct emergency operations, organize recovery effects, and direct officials of cooperating agencies.
- 4. Notify American Red Cross, or agencies in charge of evacuation centers, including food and medical facilities. Handle inquiries on status of evacuees.
- 5. Police security of area to maintain or initiate alternate vehicular traffic and to prevent looting.
- 6. Establish roadblocks to prevent unauthorized entry.
- 7. Locate additional or alternate evacuation centers, as needed.
- 8. Notification of utilities.

Responsibility

Plant Personnel, Putnam County OEM, Putnam County Sheriff, and State Police

Plant Personnel, Putnam County OEM, Putnam County Sheriff, and State Police

County OEM Director and executed by local officers

Planned by Putnam County OEM

Ranking Local Law Enforcement Officers

Planned by Putnam County OEM Director and Executed by Local Officers

Planned by the American Red Cross or Putnam County OEM Director and Executed by Local Officers

Plant Personnel

* Appropriate names, addresses, and phone numbers are provided in Appendix C.

Section C – Evacuation Notification Map

Not applicable. No non AEP structures are located within inundation area (Appendix D).

Part III - Post Evacuation Notification Action

Section A - No Failure of Dam

Should no failure occur:

Action

1. Cancel evacuation notification.

Check when notified:

- Putnam County Office of Emergency Management
- ____ DWWM Dam Safety Section (if not on-site)

Section B – Failure of Dam

Should failure occur:

Action

1. Notify agencies according to checklist below:

Check when notified:

- Putnam County Office of Emergency Management
- ____ DWWM Dam Safety Section (if not on-site)
- 2. Evacuation or assistance to persons stranded in homes due to highway/bridge washout.
- 3. Search and rescue.

4. Cleanup crews and equipment

<u>Responsibility</u>

DWWM Dam Safety Section 1-800-642-3074

Phone Phone

911 or (304) 586-4920 1-800-642-3074

Responsibility

Phone

(304) 586-4920 1-800-642-3074

Putnam County OEM * (304) 586-4920

Putnam County OEM * (304) 586-4920

Putnam County Sheriff Department (304) 586-0256

Amos Plant Personnel

Putnam County OEM * (304) 586-4920

Putnam County Sheriff Department (304) 586-0256 Amos Plant Personnel

* Appropriate names, addresses, and phone numbers are provided in Appendix C.

Part IV - Administrative and Record Keeping

Section A - Signature and Distribution List

SIGNATURE:

(Note to Preparer- The signature page of the draft plan must be signed by the dam owner/preparer and the appropriate County Office of Emergency Management Director(s) prior to submittal to Dam Safety for review and potential approval. If more than one County OEM is involved with the MEAP, additional signature statements must be added.)

County Office of Emergency Management:

As the Director of the Putnam County Office of Emergency Management (OEM), I hereby certify that I have reviewed this Monitoring and Emergency Action Plan (MEAP) and agree with the actions and responsibilities assigned to this office within this MEAP. It is noted that designated response activities may be altered during an actual event based on consideration of other emergency concerns and relative priorities.

NAME Mikyle White

Director of Putnam County OEM

TITLE

10/13/2023

DATE

Responsible Person for Distribution of the Monitoring & Emergency Action Plan:

The undersigned states he/she will distribute a copy of the Monitoring and Emergency Action Plan for the John Amos Plant Bottom Ash Pond #1A Dam within fifteen days after receipt of DWWM Dam Safety Section approval to the persons named in the Distribution List below:

NAME

Brett Guthrie

TITLE

DATE

Environmental and Laboratory Supervisor (dam owner or NRCS sponsor) 10-13-2023

CCR Emergency Action Plan Annual Meeting Documentation

Use this form to document the CCR Rule required annual face to face meeting.

Meeting was held to discuss the Emergency Action Plan for the following CCR unit(s):

John Amos Plant (AEP) Bottom Ash Complex ID#07918

Plant Personnel conducting the meeting:

| Derrick Brumfield, Brett Guthrie | |
|---------------------------------------|------------------------|
| Date: 10-13-33 Time Hel | d: 0900 |
| Attending Organization: RTNAM Co. 911 | / Emergency Management |
| Print Name: Mikyle White | Sign: Mily M |
| Print Name: Noah Aluis | Sign: Juhlia |
| Print Name: | Sign: |
| Attending Organization: AEP John Amo | s Buer Plant |
| Print Name: DECEDICE Beumfield | Sign: Dul Rufe |
| Print Name: | |
| Print Name: | Sign: |
| Attending Organization: | |
| Print Name: | Sign: |
| Print Name: | Sign: |
| Print Name: | Sign: |
| Attending Organization: | |
| Print Name: | Sign: |
| Print Name: | Sign: |
| Print Name: | Sign: |

Use multiple pages to document additional organizations or attendees.

6 × 8

Section A - Signature and Distribution List (Continued).

Signature:

The undersigned states he/she will distribute a copy of the Monitoring and Emergency Action Plan for the John E. Amos Plant Bottom Ash Complex within fifteen days after receipt of DWWM Dam Safety Section approval to the persons named in the Distribution List below:

| Name | Title | <u>Date</u> |
|------------------------------|--------------------------------|-------------|
| But & Lat (Brett Guthrie) | Environmental & Lab Supervisor | 10-13-2023 |

Distribution:

Names and addresses of all persons or agencies retaining a copy of the plan:

| <u>Name</u> | Complete Mailing Address |
|-------------------|---|
| Bryan Brunton | 1 Riverside Plaza Columbus, OH 43215 (614) 716-3090 |
| Brian Palmer | 1 Riverside Plaza Columbus, OH 43215 (614) 716-3382 |
| Paul Massie | John Amos Power Plant 1530 Winfield Road Winfield, WV 25213 (304) 759-3200 |
| Derrick Brumfield | John Amos Power Plant 1530 Winfield Road Winfield, WV 25213 (304) 759-2795 |
| Jeff Davis | John Amos Power Plant 1530 Winfield Road Winfield, WV 25213 (304) 759-3222 |
| Brett Guthrie | John Amos Power Plant 1530 Winfield Road Winfield, WV 25213 (304) 759-2799 |

| Name | Complete Mailing List |
|--|---|
| Jeff Carpenter | John Amos Power Plant 1530 Winfield Road Winfield, WV 25213 (304) 759-3642 |
| Jamie Prowse | John Amos Power Plant 1530 Winfield Road Winfield, WV 25213 (304) 759-3224 |
| Nate Ball | John Amos Power Plant 1530 Winfield Road Winfield, WV 25213 (304) 759-3274 |
| Bud Hampton | John Amos Power Plant 1530 Winfield Road Winfield, WV 25213 (304) 759-3227 |
| Jon Webster | APCO External Affairs 404 29 th Street W Charleston, WV 25387 (304) 746-2761 |
| Aaron P. Tonkery | DEP Division of Water and Waste Management EE/Dam Safety Section 2031 Pleasant Valley Rd. Fairmont, WV 26554 (304) 368-3955 ext. 1022442034 |
| Mikyle White | Putnam County Office of Emergency Management 100 Emergency Lane Winfield, WV 25213 (304) 586-4920 |
| Bobby Eggleton, Sheriff | Putnam County Sheriff's Office 9 Courthouse Street Winfield, WV 25213 (304) 586-0256 |
| West Virginia State Police Attachment Commander | 258 Courthouse Drive, Suite 10 Winfield, WV 25213 (304) 586-2000 |
| Winfield Volunteer Fire Department | 45 Main Street Winfield, WV 25213 |

<u>Name</u>

e)

Raynell Napier U.S. Army Corps of Engineers Huntington District

American Red Cross

West Virginia Emergency Management Division

Complete Mailing Address

502 8th Street Huntington, WV 25701 (304) 399-6997

113 Lakeview Drive Charleston, WV 25313 (304) 340-3650

1700 MacCorkle Ave 6th Floor Charleston, WV (304) 558-5380

Section B – Inspection Record

| Date Inspected | Inspector | Comments |
|------------------|---|---|
| October 3, 2017 | J.T. Massey-Norton AEP Sn Hydrogeologist | The impoundment is functioning as intended with no signs of potential structural weakness or other conditions that could potentially disrupt the safe operation of the impoundment. |
| July 6, 2018 | J.T. Massey-Norton AEP Sn Hydrogeologist | The impoundment is functioning as intended with no signs of potential structural weakness or other conditions that could potentially disrupt the safe operation of the impoundment. |
| May 16,2019 | J.T. Massey-Norton AEP Sn Hydrogeologist | The impoundment is functioning as intended with no signs of potential structural weakness or other conditions that could potentially disrupt the safe operation of the impoundment. |
| August 13, 2020 | Brian G. Palmer AEP Geotechnical Engineer | The impoundment is functioning as intended with no signs of potential structural weakness or other conditions that could potentially disrupt the safe operation of the impoundment. |
| October 21, 2021 | Brian G. Palmer AEP Geotechnical Engineer | The impoundment is functioning as intended with no signs of potential structural weakness or other conditions that could potentially disrupt the safe operation of the impoundment |
| October 25 ,2022 | Brian G. Palmer AEP Geotechnical Engineer | The impoundment is functioning as intended with no signs of potential structural weakness or other conditions that could potentially disrupt the safe operation of the impoundment |

25

> APPENDIX A EAP Training Record

EAP Training Record Form

| Use this form to record training sessions. File the completed form in the EAP. A thorough review of all items in the EAP should be discussed during training. Appropriate employees and EAP team | | |
|--|--|--|
| items in the EAP should be discussed during training. Appropriate employees and EAP team members should attend the training session, annually or participate in a simulated exercise. | | |
| TRAINING LOCATION: John E Amos Plant & | | |
| DATE: <u>10/25/22</u> INSTRUCTOR: E | Brian Palmer PG | |
| CLASS SIGN-IN | | |
| Training Date: October 25,2022 | Scott Sterling | |
| Training Date: October 25,2022 | Derrick Brumfield | |
| Training Date: October 25,2022 | Jack Smith | |
| Training Date: October 25,2022 | Mark Darst | |
| Training Date: October 25,2022 | John Moore | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| Summary and Commentary: Provided training to be able to identify major da reviewed various potential signs of structural d | am components of specific to the fly ash dam and eficiencies pertinent to the dam. | |

> APPENDIX B UNUSUAL OR EMERGENCY EVENT LOG

Monitor or responsible person to enter the following, as events occur:

Dam Name: John E. Amos Plant Bottom Ash Complex

When and how was the event detected?

General description of the emergency situation:

ACTIONS AND EVENT PROGRESSION

| Date | Time | Action/Event Progression | Taken by |
|------|------|--------------------------|----------|
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

Report prepared by: _____ Date: _____

29

APPENDIX C EMERGENCY CONTACTS

Notification List – Responsible Individuals (Plant and AEPSC) and List of Local Utilities John E. Amos Plant Bottom Ash Pond Complex Dam #07918

| John E. Amos Plant | | Plant Address | Plant Telephone No. |
|---|--------------------------------------|--|---------------------|
| | | 1530 Winfield Road Winfield, WV 25213 | (304) 759-3103 |
| | | or | Audinet: |
| | | PO Box 4000 St. Albans, WV 25177 | 262-3103 |
| Amos Plant Contacts: | : | | |
| Brett Guthrie Derrick Brumfield Paul Massie | | 304-759-2799, Cell: 681-28 304-759-2795, Cell: 681-31 304-759-3200, Cell: 681-31 | 7-4406 |
| Team Leaders: Nate Ball Bud Hampton Jeff Carpenter Jamie Prowse | Team 1 Team 2 Team 3 Team 4 | 304-759-3274 304-759-3227 304-759-3642 304-759-3224 | |

| AEPSC Contacts: | | |
|---|--------------|--------------|
| | Work | Cell |
| Bryan Brunton, Geotechnical Engineering Manager | 614-716-2917 | 614-202-7513 |
| Brian Palmer, Geotechnical Services | 614-716-3382 | 614-542-9701 |

Law Enforcement Contacts

| State Police | |
|------------------------------|--|
| Putnam County Sheriff | |
| Kanawha County Sheriff | |
| Winfield Police Department | |
| St. Albans Police Department | |
| Eleanor Police Department | |
| Nitro Police Department | |
| | |

Emergency Contacts

| Putnam County Health Department | |
|---|--|
| CAMC Medical Center | |
| National Response Center (chem. oil spills, chem. & biological terrorism) | |
| State Emergency Spill Notification | |
| Hazardous Materials Response | |
| Winfield Fire Department | |
| Nitro Fire Department | |
| Teays Valley Volunteer Fire Department | |
| Appalachian Power Company | |
| CSX Technology | |
| Cabot Oil and Gas | |
| Columbia Gas Transmission | |
| Ferrell Gas | |
| Mountaineer Gas | |
| Penn Virginia Oil & Gas | |
| Tennessee Gas Pipeline | |
| Union Oil & Natural Gas | |
| South Putnam PSD | |
| Verizon | |
| WV Department of Highways | |

> APPENDIX D INUNDATION MAP

